H-K Building 5 Project Number: 0980193E

t Number: 0980193E | Project: G. HEILEMAN BREWERY "E"

Date Inspected: 03/28/89 Inspector: MARK VOTH



Building Number: 36

Building Name: WAREHOUSE

SEATTLE, WASHINGTON 98134

Building Type: WAREHOUSE

Year Constructed: 1964

					
[*****	AREA NUMBER: 01	AREA DESCRIPTION: 1st Floor	AREA AVERAGE % ASBESTOS: 15%	********
1					

LOCATION OF THE MATERIAL	SAMPLE NUMBER	ASB	MATERIAL DESCRIPTION	O&M CODE	UNITS OF QUANTITY MEASURE	PIPE ID	EXP POT PL	REMOVAL COSTS	REPLACEMENT COSTS	TOTAL COSTS
along center-north to south-at ceiling along center-north to south-at ceiling along east wall-at ceiling along east wall-at ceiling	01-356177 01-356177 01-356177 01-356177 01-356178 01-356179	15% 15% 15% 20% 15%	mjp on non-suspect pipe cover mjp on non-suspect pipe cover mjp on non-suspect pipe cover mjp on non-suspect pipe cover	OMA OMA OMA OMA	5 4 in. 0.0. 3 6 in. 0.0. 2 4 in. 0.0. 8 6 in. 0.D.	LPS/R LPS/R LPS/R	25 III 25 III	\$116 \$56 \$309	\$68 \$31 \$182	\$218 \$184 \$87 \$491
along east wall-at ceiling along east wall-at ceiling along west wall-at ceiling along west wall-at ceiling	02-356180 02-356180 02-356180 02-356180 02-356181 02-356182	10% 10%	mjp on non-suspect pipe cover mjp on non-suspect pipe cover mjp on non-suspect pipe cover mjp on non-suspect pipe cover	OMA OMA OMA OMA	9 4 in. 0.D. 4 6 in. 0.D. 19 4 in. 0.D. 4 6 in. 0.D.	DR DR DR DR	25 111 25 111 25 111 25 111 25 111 25 111		\$140 \$91 \$297 \$91	\$393 \$246 \$831 \$246

AREA COMMENTS

AREA # 01 TOTAL \$1,718 \$978 \$2,696

The material is in good condition with minor contact and water damage. The material is approximately 12' to 15' from the floor. At a minimum, it is recommended that the material be repaired and monitored. If removal is planned, glove bag removal procedures are recommended. This appears to be a high traffic area.

ı	BUILDING # 36	TOTAL	\$1,718	\$978	\$2,696
4					,